

Radon Inspection Report

Measurement of Radon Concentration in Indoor Air

Report No.: 2700009174202002270753
 Serial No.: 2700009174

Report Generated Date: 2/27/20

Measurement Address:

1015 W Castleton Dr
 North Salt Lake , UT 84054
 United States

Measurement performed by:

Robert Daniel Egbert
 Castleview Home Inspections LLC
 P.O. Box 160231
 Clearfield , UT 84016
 CastleviewInspections@gmail.com
 USA

Ventilation: Mechanical

Building type: House

Building year: 2008

Room	Floor	Measurement Start	Measurement End	Measured Value
Living room	Ground floor	2/24/20, 3:49 PM	2/26/20, 3:49 PM	1.3 pCi/L

North Salt Lake

February 27, 2020

Location

Date

Signature



Detailed Measurement Data

	Min	Max	Average
Radon [pCi/L]	0.0	2.6	1.3
Temperature [°F]	59.4	66.6	60.7
Humidity [%rH]	23	30	24
Pressure [kPa]	87.89	88.76	88.49

Radon measurements for hour 1 to hour 48

Hour	Radon conc. [pCi/L]
2/24/20, 3:49 PM	0.8
2/24/20, 4:49 PM	1.1
2/24/20, 5:49 PM	0.8
2/24/20, 6:49 PM	0.5
2/24/20, 7:49 PM	1.8
2/24/20, 8:49 PM	0.2
2/24/20, 9:49 PM	1.3
2/24/20, 10:49 PM	2.6
2/24/20, 11:49 PM	1.5
2/25/20, 12:49 AM	1.3
2/25/20, 1:49 AM	1.8
2/25/20, 2:49 AM	2.3
2/25/20, 3:49 AM	1.5
2/25/20, 4:49 AM	1.3
2/25/20, 5:49 AM	1.5
2/25/20, 6:49 AM	1.0
2/25/20, 7:49 AM	0.7
2/25/20, 8:49 AM	1.3
2/25/20, 9:49 AM	1.3
2/25/20, 10:49 AM	2.6
2/25/20, 11:49 AM	1.0
2/25/20, 12:49 PM	1.0
2/25/20, 1:49 PM	0.5
2/25/20, 2:49 PM	1.5

Hour	Radon conc. [pCi/L]
2/25/20, 3:49 PM	2.0
2/25/20, 4:49 PM	0.5
2/25/20, 5:49 PM	2.3
2/25/20, 6:49 PM	0.0
2/25/20, 7:49 PM	1.0
2/25/20, 8:49 PM	1.8
2/25/20, 9:49 PM	2.6
2/25/20, 10:49 PM	1.3
2/25/20, 11:49 PM	0.7
2/26/20, 12:49 AM	1.0
2/26/20, 1:49 AM	1.0
2/26/20, 2:49 AM	0.2
2/26/20, 3:49 AM	1.0
2/26/20, 4:49 AM	1.5
2/26/20, 5:49 AM	1.0
2/26/20, 6:49 AM	2.6
2/26/20, 7:49 AM	1.8
2/26/20, 8:49 AM	0.7
2/26/20, 9:49 AM	2.0
2/26/20, 10:49 AM	0.7
2/26/20, 11:49 AM	1.8
2/26/20, 12:49 PM	2.3
2/26/20, 1:49 PM	0.5
2/26/20, 2:49 PM	1.5

Pressure Chart

